

336 Cherry Hill Circle West

Aylett, Virginia 23009 Phone: 804-761-4248

FrazierConsulting@gmail.com

Licensed Class A - RBC/CBC DEPOR # 2705169996

EIN# 83-1821991

## **DAILY REPORT**

## WESTMORELAND COUNTY HIGH SCHOOL

Date: 04/21/2021

Weather: 54 degrees at 14:30hrs. Light Rain. High of 59 degrees today.

Hours Worked: 14:30hrs – 16:00hrs (1.5hrs) Site Visit.

I did not visit the site yesterday.

**Beuchert Excavation:** I counted three (3) men on site today. They continue to move dirt around the site, grading and reworking the Retention Ponds.

**Industrial Concrete:** Five (5) men are on site today. The are setting the steel rebar for the Loading Dock Wall. The Footer will be poured tomorrow.

**J.D. Long, Masons:** Fourteen (14) Masons are on site today laying Brick on the South and West sides of Area E.

**Hazzard Electric:** Seventeen (17) men are on site and they continue to work in Area A & B & D running conduit and pulling wire.

**Colonial Webb**: Forty-Six (46) men are on site today. They are insulating pipe in Area B,  $1^{st}$  floor, connecting Roof Drains in Areas A & B. They are also running HVAC Duct in Area A,  $1^{st}$  floor.

**Weldon Steel**: Six (6) men are on site today. They continue to set and weld steel In Area C. A couple of guys are also laying Roof Decking in Area C.

**JP Construction:** Eighteen (18) men are on site today. They continue to erect interior walls and hanging sheet rock on the 1<sup>st</sup> floor of Area A. They are also installing batt Insulation in Area A 1<sup>st</sup> floor. A crew is also framing the Parapet wall on the eastside of Area A Stairwell.

**AAR Roofing:** Four (4) men are on site today. They have been working on the roof of Area A.

**Tailored Foam:** Two (2) men are on site today. They have been spraying foam on the Eastside of Area.

**FG & M:** Four (4) men are on site. They are working on the curtain wall on the Westside of Area B.

**United Sprinkler:** One (1) man are on site today running Sprinkler pipe on the 2<sup>nd</sup> floor of Area

**S&S Concrete Cutting Company:** I did not observe anyone on site during my visit today.

**Linear Surveyors:** I did not observe anyone on site today.

Hillis-Carnes. I did not observe anyone on site during my visit.

Questions to or from Branch Builds: Brian left the site early today and was not here when I arrived. I met with Jake and Cooper in the trailer. Jake and I examined the Stair Tread Mockup that was completed yesterday. Copper and I discussed the project and what was going on today.

**Compliance with Contract Documents**: No noted discrepancies.

**DEQ Reports**: Last Inspection was on 03/09/2021. The Report has been distributed and DEQ turned over the Inspection results to the DEQ Enforcement Division.

## **Reviewed emails:**

Hillis-Carnes Concrete Break Report Hillis-Carnes Grout Inspection/Compression Strength Test Hillis-Carnes Field Reports (Concrete and Steel) Submittals - #26 50 00-2.1
RFIs Patrick Byrne Change Order/PCOs/Pay App - PCO #44
Changes in Procore Weekly Submittal Status Report Weekly RFI Status Update Weekly Daily Log Summary -



 ${\it Photo}~1-{\it Stair}~tread~{\it Mockup}~has~been~completed.$ 



Photo 2 - The East side of Area A has been foamed.



Photo 3 - The Masons are bringing up the brick on the South side of the  $\operatorname{\mathsf{Gym}}$ 



Photo 4 - Steel continues to be set in Area C




Photo 5 - Metal Decking is being laid in Area C




Photo 6 - Walls have been insulated and now are being sheet rocked on both sides in Area A, 1st floor.




Photo 7 - Interior walls being framed on the 2nd Floor or Area A



Photo 8 - Roofers are making progress on the Roof of Area A




Photo 9 - Parapet Wall being framed in Area A



Photo 10 - Door Frame has been set at the top of Stairwell #2.




Photo 11 - Frame has been set on the West side of Area B