



**COMMONWEALTH  
BUILDING SOLUTIONS, LLC**

336 Cherry Hill Circle West

Aylett, Virginia 23009

Phone: 804-761-4248

FrazierConsulting@gmail.com

Licensed Class A - RBC/CBC

DEPOR # 2705169996

EIN# 83-1821991

**FIELD REPORT**

**WESTMORELAND COUNTY HIGH SCHOOL**

Date: 12/30/2021

Weather: 56 degrees. Cloudy. High of 57 degrees today. Rain overnight and early this morning.

Hours Worked: 14:00 – 15:30hrs (1.5hrs)

When I arrived on site today there were only approximately five or six vehicle present.

While walking the site I noted that there were four members of the Flooring sub present laying tile in the Entry way between E103 Boy's Toilet and E104 Girls Toilet. There were also two guys setting Cabinetry on the second floor of Area A. Know one else was observed during my visit.

**Conversations with Branch Builds:** No one from Branch Builds was present during my visit

**Compliance with Contract Documents:** No noted discrepancies.

**DEQ Reports:** A re-inspection of the site was conducted on November 29<sup>th</sup>, 2021.

**Reviewed emails:**

**Hillis-Carnes Concrete Break Report -**

**Hillis-Carnes Grout Inspection/Compression Strength Test – 12/27/2021, 12/29/2021**

**Hillis-Carnes Field Reports – 12/21/2021**

**Hillis-Carnes Bio Retention Pond Reports –**

**Submittals –**

**RFIs – RFI #354, #362**

**Patrick Byrne –**

**Alexes Lee –**

**Tara Delaney –**

**Change Order/PCOs/Pay App –**

**Weekly Submittal Status Report: 12/23/2021**

**Weekly RFI Status Update – 12/23/2021**

**Weekly Daily Log Summary – 12/223/2021**

**PCO Log – 12/23/2021**



*Photo 1 - Work continues on and around the Grand Staircase.*



Photo 2 - Tile being laid in the Entryway of E103/E104



Photo 3 - Bleacher on the East side of Gym have been completed.




Photo 4 - Bleachers are being constructed on the West side of the Gym



Photo 5 - Wall Tile has been laid in E104 Girls Locker Room



Photo 6 - Girls Locker Room - E104



Photo 7 – E124 - Girls Locker Room - Wall Tile has been laid.





*Photo 8 - Wall Tile has been laid in E126 Boy's Locker Room*



Photo 9 - Wall Tile E126 - Boys Locker room



Photo 10 - E126



Photo 11 - Kitchen Sinks, Tables, Equipment stage in Auditorium



Photo 12 - Stainless steel table & Equipment stored in Auditorium



*Photo 13 - Kitchen Reach-in Cooler & Equipment stored in Auditorium*



*Photo 14 - D154 - Mechanical Room is being painted.*



*Photo 15 - Border Bulkhead has been painted Orange on the 2<sup>nd</sup> floor of Area B.*