



Branch Builds - NOVA Office  
 Job #: 11902 Washington & Lee HS Replacement  
 16762 Kings Highway Route 3  
 Montross , Virginia 22520

## Weekly Daily Log Summary

A summary of the last 7 daily logs.

### Manpower Log

Date	Company	Workers	Total Hours	Comments
03/19/2021	JP Construction Inc.	4	32	Interior wall framing.
03/19/2021	JP Construction Inc.	1	8	Interior wall blocking.
03/19/2021	JP Construction Inc.	1	8	Clean up and stocking.
03/19/2021	JP Construction Inc.	3	24	Supervisión and layout.
03/18/2021	JP Construction Inc.	4	32	Interior Wall framing
03/18/2021	JP Construction Inc.	2	16	2nd B Interior Blocking
03/18/2021	JP Construction Inc.	1	8	Clean up
03/18/2021	JP Construction Inc.	3	24	Supervision, Lay out
03/18/2021	J.D. Long Masonry of VA Inc.	1	8	unable to do anything due to the weather it rain most of the day unloaded two loads of brick and took scaffold out the Mechanical room in zone 1-
03/18/2021	Colonial Webb Contractors	27	270	Rough and domestic water zone 5,overhead duct Rough in zone 4 second-floor, low pressure pipe in zone 5 first floor, connect mechanical piping to VAV boxes zone 5 first floor, hang steel piping zone 3, tie-in controls to VAV boxes zone 4 first floor, insulate low pressure pipe zone 5 first floor.
03/18/2021	Hazzard Electrical, LLC	10	80	Zone 5 finish up panel and feeders wall rough in for science labs and overhead conduit Zone 4-2 overhead conduit and branch wire
03/18/2021	Weldon Steel Corporation	7	56	worked on pour stops
03/18/2021	United	2	16	2nd floor sprinkler rough in



Branch Builds - NOVA Office  
 Job #: 11902 Washington & Lee HS Replacement  
 16762 Kings Highway Route 3  
 Montross , Virginia 22520

Date	Company	Workers	Total Hours	Comments
	Sprinkler Company, Inc.			
03/18/2021	Fredericksburg Glass & Mirror, Inc.	4	32	Misc.
03/17/2021	Hazzard Electrical, LLC	9	72	Zone 1 chase mason,panel layout for pads in d158 Zone 4-2 branch wire and overhead conduit Zone 5-1 branch conduit
03/17/2021	Colonial Webb Contractors	27	270	Rough and domestic water zone five, storm tie and outside auditorium, overhead duct Rough in zone 4 second-floor, low pressure pipe in zone five first floor, connect mechanical piping to VAV boxes zone five first floor, hang steel piping zone one, tie-in controls to VAV boxes zone four first floor, insulate low pressure pipe zone 5 first floor.
03/17/2021	Weldon Steel Corporation	7	56	installing steel frames in zone 1 installing decking in zone 2 setting lintel beams in zone 2
03/17/2021	United Sprinkler Company, Inc.	2	16	sprinkler rough in zone 3
03/17/2021	Tailored Foam, INC.	2	16	spray foaming zone 4
03/17/2021	Fredericksburg Glass & Mirror, Inc.	4	32	installing storefront in zone 5
03/17/2021	JP Construction Inc.	2	16	Hang sheathing
03/17/2021	JP Construction Inc.	2	16	Z furring installation
03/17/2021	JP Construction Inc.	2	16	Roof blocking
03/17/2021	JP Construction Inc.	1	8	Clean up
03/17/2021	JP Construction Inc.	3	24	Supervision, Lay out
03/16/2021	JP Construction Inc.	1	8	Clean up
03/16/2021	JP	3	24	Supervision, Lay out

Date	Company	Workers	Total Hours	Comments
	Construction Inc.			
03/16/2021	JP Construction Inc.	2	16	Roof blocking installation
03/16/2021	JP Construction Inc.	2	16	Framing low wall on roof, hang sheathing
03/16/2021	JP Construction Inc.	2	16	Z channel installation
03/16/2021	Weldon Steel Corporation	7	56	setting columns and beams and bar joist in zone 2
03/16/2021	United Sprinkler Company, Inc.	2	16	testing line in zone 4
03/16/2021	Tailored Foam, INC.	2	16	installing air barrier transition membrane
03/16/2021	Colonial Webb Contractors	26	260	Rough and domestic water zone five, storm tie and outside mechanical room, overhead storm piping in zone one, overhead duct Rough in zone 4 second-floor, low pressure pipe in zone five first floor, connect mechanical piping to VAV boxes zone five first floor, hang steel piping zone one, tie-in controls to VAV boxes zone four first floor, insulate low pressure pipe zone 5 first floor.
03/16/2021	J.D. Long Masonry of VA Inc.	19	152	Continue interior block work mechanical rooms Zone 1- continue laying block in rooms D111&D103 installed base flashing at roof south elevation N.2 line in zone 3 cut out and re install storefront block jam @door E10A&B grouted and set embeds for storefront at 10'8 16line CRANE STILL SETTING STEEL IN ZONE 2
03/16/2021	Hazzard Electrical, LLC	10	80	Chase mason zone 1 Overhead conduit zone 5 Overhead conduit and wire in zone 4-2 Pad layout and conduit termination
03/15/2021	JP Construction Inc.	3	24	Supervision, Lay out
03/15/2021	JP Construction Inc.	1	8	Clean up
03/15/2021	JP Construction Inc.	2	16	Z furring installation
03/15/2021	JP Construction Inc.	2	16	Roof blocking installation

Date	Company	Workers	Total Hours	Comments
03/15/2021	JP Construction Inc.	2	16	Hang Sheathing on exterior walls/ Roof blocking
03/15/2021	Hazzard Electrical, LLC	8	64	Pad layout zone 1 Chase mason zone 1 ,2 Zone 5 overhead conduit Zone 4 -2 overhead conduit
03/15/2021	Colonial Webb Contractors	27	270	Rough and domestic water zone five, storm tie and outside mechanical room, overhead storm piping in zone one, overhead duct Rough in zone 4 second-floor, hang offset piece for zone three hallway, low pressure pipe in zone five first floor, connect mechanical piping to VAV boxes zone five first floor, hang steel piping zone one, tie-in controls to VAV boxes zone four first floor, insulate mechanical piping zone for first floor.
03/15/2021	United Sprinkler Company, Inc.	2	16	stairwell 4 finishing up pipping for test
03/15/2021	Fredericksburg Glass & Mirror, Inc.	2	16	misc. work
03/15/2021	J.D. Long Masonry of VA Inc.	21	168	ZONE 1- interior block work north mechanical rooms East side. reloaded scaffold and clean up in room. D131. need door frame set D130 patch joints pockets inside Auditorium. high roof and point up along the way South elevation at roof level grouted behind 4" block at brick veneer N.2 block work in rooms D111&103 can't do anything in Zone 2- crane setting steel in Zone 3 reinstall Door jam block where it had to be cut out to enlarge opening continue hanging flashing at window heads south elevation Zone 4-
03/12/2021	JP Construction Inc.	2	16	Roof blocking
03/12/2021	JP Construction Inc.	2	16	Hang Sheathing and roof blocking
03/12/2021	JP Construction Inc.	2	16	Z furring installation North elevation
03/12/2021	JP Construction Inc.	2	16	Clean up
03/12/2021	JP Construction Inc.	2	16	Supervision, Lay out
03/12/2021	Colonial Webb Contractors	1	8	laying on sleeves following the mason



**Notes Log**

Date	Created By	Comments
03/19/2021	Douglas Zelaya	Do to weather conditions we are unable to work on exterior walls.

**Weather Log**

Date	Measured Temperature High	Measured Temperature Low	Measured Precipitation Since Midnight	Delay	Measured Wind Speed Average
03/19/2021	49	38	0.1828	Yes	14.05
03/18/2021	58	46	0.9324	Yes	6.45
03/18/2021	58	46	0.9324		6.45
03/17/2021	54	40	0.015		4.4
03/16/2021	44	36	0.087		5.65
03/15/2021	49	32	0.0573		7.8
03/14/2021	65	35	0.0		9.03
03/13/2021	59	43	0.0		6.18
03/12/2021	72	55	0.0275		8.41

**Photos**

Photos From Daily Log

**Uploaded On**  
03/12/2021



Photos From Daily Log

**Uploaded On**  
03/12/2021




Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily Log

Uploaded On  
03/12/2021





Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily  
Log

Uploaded On  
03/12/2021



Photos From Daily  
Log

Uploaded On  
03/12/2021






Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily Log

Uploaded On  
03/12/2021





Photos From Daily  
Log

Uploaded On  
03/12/2021



Photos From Daily  
Log

Uploaded On  
03/12/2021



Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily Log


Uploaded On  
03/12/2021





Photos From Daily Log

Uploaded On  
03/12/2021




Photos From Daily Log

Uploaded On  
03/12/2021




Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily Log

Uploaded On  
03/12/2021






Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily Log

Uploaded On  
03/12/2021



Photos From Daily Log

Uploaded On  
03/16/2021



Photos From Daily Log

Uploaded On  
03/16/2021





Photos From Daily Log

Uploaded On  
03/16/2021



Photos From Daily Log

Uploaded On  
03/16/2021



Photos From Daily Log

Uploaded On  
03/16/2021



Photos From Daily Log

Uploaded On  
03/16/2021





Photos From Daily Log

Uploaded On  
03/16/2021



Photos From Daily Log

Uploaded On  
03/16/2021



Photos From Daily Log

Uploaded On  
03/16/2021



Photos From Daily Log

Uploaded On  
03/16/2021






Photos From Daily Log

Uploaded On  
03/16/2021



Photos From Daily Log

Uploaded On  
03/17/2021




Photos From Daily Log

Uploaded On  
03/17/2021



Photos From Daily Log

Uploaded On  
03/17/2021





Photos From Daily  
Log

Uploaded On  
03/17/2021



Photos From Daily  
Log

Uploaded On  
03/17/2021




Photos From Daily Log

Uploaded On  
03/17/2021



Photos From Daily Log

Uploaded On  
03/17/2021





Photos From Daily Log

Uploaded On  
03/17/2021



Photos From Daily Log

Uploaded On  
03/17/2021



Photos From Daily Log

Uploaded On  
03/17/2021



Photos From Daily Log

Uploaded On  
03/17/2021






Photos From Daily Log

Uploaded On  
03/17/2021



Photos From Daily Log

Uploaded On  
03/17/2021



Photos From Daily Log

Uploaded On  
03/17/2021



Photos From Daily Log

Uploaded On  
03/18/2021





Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021





Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021





Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021




Photos From Daily  
Log

Uploaded On  
03/18/2021



Photos From Daily  
Log

Uploaded On  
03/18/2021





Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021






Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021





Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021





Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021





Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily  
Log

Uploaded On  
03/18/2021



Photos From Daily  
Log

Uploaded On  
03/18/2021





Photos From Daily Log

Uploaded On  
03/18/2021




Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021






Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021





Photos From Daily Log

Uploaded On  
03/18/2021



Photos From Daily Log

Uploaded On  
03/18/2021

